IPM GE

00862.022294

PATENT

APR 1 1 2005	IN THE UNITED STATES PATE	NT AND TE	RADEMARK OFFICE
PATENT & TRANSIN I	e Patent of:)	
		:	Examiner: R. Zacharia
DAISHI SAIKI ET AL.)	·
		:	Group Art Unit: 1773
Appl. No.: 09/897,014)	
		:	
Filed: July 3, 2001)	
-	MAIL THE AMERICA CORRESPONDE	:	
For	· Mobile in Breed of the of the)	
	RESIN MOLDED PRODUCT	:	
	AND METHOD OF)	
	MANUFACTURING	:	
	MULTILAYERED STRUCTURE)	
	RESIN MOLDED PRODUCT	:	
)	
U.S	S. Patent No.: 6,838,131 B2	:	
)	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Issued: January 4, 2005

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

The following minor errors have been noted in the above-identified patent:

April 8, 2005

COVER PAGE [56] OTHER PUBLICATIONS

Line 2, "83(7) Kunstsoff" should read --83(7) Kunststoffe--.

COLUMN 4

Line 65, "produced," should read --product,--.

COLUMN 6

Line 37, "a ejector" should read --an ejector--, and Line 38, "a ejector" should read --an ejector--.

COLUMN 8

Line 29, "avoids" should read --prevents--.

COLUMN 9

Line 7, "material-flows" should read --material flows--.

COLUMN 10

Line 52, "calori-" should read --colori- --.

These errors appear to be relatively insignificant and, therefore, we do not believe it is necessary to request a Certificate of Correction. However, it is requested that this paper be placed in the filewrapper of the above-identified patent.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

sson M. Okun

Attorney for Patentees Registration No.: 48,512

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_MAIN 492117v1